



Detail Photo No. 1 - Overall view of East Elevation from 1st Avenue.



Detail Photo No. 2 – Close-up of curtain wall on East Elevation.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
1 of 21



Detail Photo No. 3 - Overall view of East Elevation parapet exterior at top of building.



Detail Photo No. 4 – Overall view of East Elevation parapet exterior at 8th Floor setback roof.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001


DATE
September 15, 2017

TITLE
Detail Photos

PAGE
2 of 21




Detail Photo No. 5 - Overall view of East Elevation transition from curtain wall to granite clad wall.



Detail Photo No. 6 – Overall view of North Elevation curtain wall detailing.



Detail Photo No. 7 - Overall view of North Elevation parapet exterior at top of building.



Detail Photo No. 8 – Overall view of North Elevation curtain wall detailing.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
4 of 21



Detail Photo No. 9 - Overall view of North Elevation curtain wall detailing.



Detail Photo No. 10 – Overall view of North Elevation curtain wall detailing.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
5 of 21



Detail Photo No. 11 - Overall view of North Elevation parapet exterior at 7th Floor Setback Roof.



Detail Photo No. 12 – Overall view of North Elevation parapet exterior at 7th Floor Setback Roof.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
6 of 21



Detail Photo No. 13 - Overall view of North Elevation, lower floors.



Detail Photo No. 14 – Overall view of South Elevation.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001


DATE
September 15, 2017

TITLE
Detail Photos

PAGE
7 of 21



Detail Photo No. 15 - Overall view of South Elevation, curtain wall detailing.



Detail Photo No. 16 – Overall view of South Elevation, curtain wall detailing.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP


PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
8 of 21



Detail Photo Nos. 17a & b - Overall view of South Elevation, exterior face of 8th Floor Setback roof parapet at left; Main Roof parapet at right.



Detail Photo No. 18 – Overall view of South Elevation, masonry façade at Loading Dock entry.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP


PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
9 of 21



Detail Photo No. 19 - Overall view of South Elevation, masonry façade at Loading Dock entry.



Detail Photo No. 20 – Overall view of South Elevation, masonry façade at Loading Dock entry – note open joints.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
10 of 21



Detail Photo No. 21 - Overall view of South Elevation, granite façade at Church entry.



Detail Photo No. 22 – Overall view of South Elevation, granite façade at ground floor.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP


PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
11 of 21



Detail Photo No. 23 - Overall view of West Elevation, curtain wall detailing.



Detail Photo No. 24 – Overall view of West Elevation, parapet exterior at top of building.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
12 of 21



Detail Photo Nos. 25a & b - Overall view of West Elevation.



Detail Photo No. 26 – Overall view of West Elevation, lower floors.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP


PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
13 of 21



Detail Photo No. 27 - Overall view of West Elevation, lower floors, masonry facade.



Detail Photo No. 28 – Detail view of West Elevation, loose mortar joint.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP


PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
14 of 21




Detail Photo No. 29 - Overall view of South Recessed Elevation, masonry facade.



Detail Photo No. 30 – Detail view of cracked brick and loose mortar joints.




Detail Photo No. 33 – Main Roof looking north.



Detail Photo No. 34 – Main Roof looking south.



Detail Photo No. 33 – Main Roof – parapet height at 38½”.



Detail Photo No. 34 – Main Roof looking south at window washing track.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
17 of 21



Detail Photo No. 35 – 8th Floor Setback Roof looking east.



Detail Photo No. 36 – 8th Floor Setback Roof - parapet height at 41".



Detail Photo No. 37 – 7th Floor Setback Roof looking west.



Detail Photo No. 38 – 7th Floor Setback Roof - parapet height at 41½”.



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
19 of 21



Detail Photo No. 39 – 3rd Floor Setback Roof looking west.



Detail Photo No. 40 – 3rd Floor Setback Roof - parapet height at 44".



Detail Photo No. 41 – Main Roof parapet – deteriorated mortar joints.



Detail Photo No. 42 – 8th Floor Setback Roof parapet – deteriorated mortar joints..



ENGINEERS & ARCHITECTS
129 West 27th Street, 5th FL.
New York, New York 10001
tel. 212-254-0030, fax. 212 4775978
www.gmsllp.com

GILSANZ . MURRAY . STEFICEK . LLP

PROJECT
1005 1st Avenue, New York, NY
Cycle 8 FISP Inspection

PROJECT No.
16492-001

DATE
September 15, 2017

TITLE
Detail Photos

PAGE
21 of 21