

8/28/2013
082013HPD Building, Registration & Violation Services --- Select --- [Home](#)**The selected address: 336 EAST 56 STREET, Manhattan 10022**

HPD# 14417 Active	Range 336-336	Block 01348	Lot 0035	CD 6	CensusTract 10800	Stories 4	A Units 6	B Units 0	Ownership PVT	Registration# 117723	Class A
----------------------	------------------	----------------	-------------	---------	----------------------	--------------	--------------	--------------	------------------	-------------------------	------------

Other Units**Building Registration Summary Report**Find Apartment# **Property Owner Registration Information****Charges**

Owner	Last Reg Dt Reg Expire Dt	Organization	Last Nm	First Nm	House No	Street Nm	Apt	City	State Zip
Head Officer	03/10/2012 09/01/2013	EDELSTEIN	WALTER	444	MADISON AVE	1805	NEW YORK	NY	10022
Officer	03/10/2012 09/01/2013	LEFKOWITZ	RICHARD	444	MADISON AVE	1805	NEW YORK	NY	10022
Corporation	03/10/2012 09/01/2013	336 EAST 56TH ST REALTY LLC		444	MADISON AVE	1805	NEW YORK	NY	10022
Managing Agent	03/10/2012 09/01/2013	336 EAST 56TH REALTY LLC	ROSENBERG ALAN	444	MADISON AVE	1805	NEW YORK	NY	10022

Map**Complaint Status****Complaint History****Carbon Monoxide Certificate****Litigation/Case Status****All Open Violations****Open Violations - ALL DATES**There are 21 Violations. Arranged by category: **A class: 9 B class: 10 C class: 2 I class: 0****For Definitions of the columns indicated below, select glossary under the Services option (located at the upper right).****To sort the columns, click on their underlined headers below in the blue area.****prior year Open Viol.'s**

Apt Story	Reported Date, nov ISSUED Date	Hzrd Class	Order no	Violation ID, NOV ID	Violation Description	Status	Certify By Date
1 2	2013/06/03 2013/06/05	B	508	9857342 4631769	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color north wall in the bathroom located at apt 1, 2nd story, 2nd apartment from north at east	NOV LATE 2013/08/20	2013/07/24 2013/08/20

Ecertification**I-Card Images****Property Registration Assistance**

1 2	2013/06/03 2013/06/05	C	508	9857352 4631770	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color ceiling in the bathroom located at apt 1, 2nd story, 2nd apartment from north at east	1 NO ACCESS 2013/07/11	2013/06/18 2013/06/18
1 2	2013/06/03 2013/06/05	B	508	9857353 4631769	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color ceiling in the 1st room from north located at apt 1, 2nd story, 2nd apartment from north at east	NOV LATE 2013/08/20	2013/07/24 2013/08/20
1 2	2013/06/03 2013/06/05	A	529	9857355 4631768	§ 27-2005 adm code refit lower window sash in the 1st room from north located at apt 1, 2nd story, 2nd apartment from north at east	NOV SENT 2013/06/05	2013/09/22
- 1	2013/06/03 2013/06/05	C	510	9857450 4631770	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of uncaped steam line at public hall, 1st story	1 NO ACCESS 2013/07/11	2013/06/18 2013/06/18
1 2	2013/06/03 2013/06/05	B	550	9857394 4631769	§ 27-2005 hmc:trace and repair the source and abate the nuisance consisting of mold ... at ceiling and north wall approx. 15 sq. ft. in the bathroom located at apt 1, 2nd story, 2nd apartment from west at north	NOV LATE 2013/08/20	2013/07/24 2013/08/20
1 2	2013/06/03 2013/06/05	B	508	9857399 4631769	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color east , south and west wall in the bathroom located at apt 1, 2nd story, 2nd apartment from west at north	NOV LATE 2013/08/20	2013/07/24 2013/08/20
1 2	2013/06/03 2013/06/05	B	702	9857400 4631769	§ 27-2045 adm code repair or replace the smoke detector missing in the entire apartment located at apt 1, 2nd story, 2nd apartment from west at north	NOV LATE 2013/08/20	2013/07/24 2013/08/20
1 2	2013/06/03	B	1502	9857408	§ 27-2046.1, 2046.2 hmc: provide an approved	NOV LATE 2013/07/24	2013/07/24

	2013/06/05	4631769	and operational carbon monoxide detecting device, installed in accordance with applicable law and rules. in the entire apartment located at apt 1, 2nd story, 2nd apartment from west at north	2013/08/20	2013/08/20
- 966	1982/01/20 1982/02/28	A 703	2519574 431099	d26-20.08,20.09 adm code file certification of satisfactory installation of smoke detecting device in accordance with h.p.d. rules and regulations.	1 NO ACCESS 1982/06/23 2010/04/27
--	1979/04/11 1979/06/18	A 579	2519571 431098	d26-16.01 adm code repair the leaky and/or defective faucets basin 4 sty front apt bathroom.	1 NO ACCESS 1979/10/11 2010/04/27
--	1979/04/11 1979/06/18	A 556	2519572 431098	d26-12.01 adm code paint with light colored paint to the satisfaction of this department walls & clg of front room 4 sty front apt.	1 NO ACCESS 1979/10/11 2010/04/27
--	1979/04/11 1979/06/18	A 501	2519573 431098	d26-10.01 adm code properly repair the broken or defective wood clg of closet pvt hall 4 sty front apt.	1 NO ACCESS 1979/10/11 2010/04/27
4F -	1978/04/26 1978/05/29	B 505	2519568 431097	d26-10.01 adm code replace with new the broken or defective glass of upper sash at center window of front room 4 sty front apt 4f. , section " "	1 NO ACCESS 1978/07/23 2010/04/27
4F -	1978/04/26 1978/05/29	B 510	2519569 431097	d26-10.01 adm code abate the nuisance consisting of concealed leak at clg of closet in front pvt hall 4 sty front apt 4f. , section " "	1 NO ACCESS 1978/07/23 2010/04/27
4F -	1978/04/26 1978/05/29	B 508	2519570 431097	d26-10.01 adm code repair the broken or defective plastered surfaces and paint in a uniform color west wall & clg of front room 4 sty front apt 4f. , section " "	1 NO ACCESS 1978/07/23 2010/04/27
2R -	1978/04/17 1978/05/08	A 508	2519563 431095	d26-10.01 adm code repair the broken or defective plastered surfaces and paint in a uniform color clg & walls 2 sty rear apt 2r rear room. , section " "	1 NO ACCESS 1978/08/31 2010/04/27
2R -	1978/04/17 1978/05/08	A 505	2519564 431095	d26-10.01 adm code replace with new the broken or defective sash chain 2 sty rear apt 2r rear room west window. , section " "	1 NO ACCESS 1978/08/31 2010/04/27
2R -	1978/04/17 1978/05/08	B 509	2519565 431096	d26-10.01 adm code properly secure the loose window glass 2 sty rear apt 2r rear room. , section " "	1 NO ACCESS 1978/07/02 2010/04/27
2R -	1978/04/17 1978/05/08	A 501	2519566 431095	d26-10.01 adm code properly repair the broken or defective and or unbalanced sash at 2 sty rear apt 2r rear room window. , section " "	1 NO ACCESS 1978/08/31 2010/04/27
2R -	1978/04/17 1978/05/08	A 529	2519567 431095	d26-10.01 adm code refit door at entrance to 2 sty rear apt 2r. , section " "	1 NO ACCESS 1978/08/31 2010/04/27

