

GM Pump Repair, Inc.  
 389 Wild Avenue, Suite A  
 Staten Island, N.Y. 10314  
 718-331-5067, Fax#718-331-3060  
 GMPump@aol.com

# Invoice

Date	Invoice #
5/30/2019	10058

Bill To	Ship To	
534 West42nd St Condos C/O Livingston Mgmt 225 West 35th St. 14th floor New York, N.Y. 10001	Job: SAME	
	P.O. No.	Terms
		upon receipt

Qty	Description	Item	Amount
	5/29/19- Reset Tornatech Fire pump controller S/N Z44480. Attempted to repack pump, it was found that the Fire pump needs to be rebuilt.	Cost	400.00T

	<b>Sales Tax (8.875%)</b>	\$35.50
	<b>Total</b>	\$435.50
	<b>Payments/Credits</b>	\$0.00
	<b>Balance Due</b>	\$435.50