

The 2 rolls that were knitted with 40 denier in front and 50 denier in back are:

065762 (180)

065764 (178)

The yarn mix-up was discovered, and we have taped out and put back the proper sets where they belong.

We couldn't even notice a difference in the fabric, and we hope that you are able to work through this issue as we go forward.

Thank You,

-Howard Cumins, VP-COO

(336) 622-1000 office

(201) 745-4000 mobile