



**DIVERSIFIED**  
TESTING LABORATORIES, INC.  
WORLDWIDE SERVICE

“We Test Per Your Request”

336 WEST FRONT STREET  
P.O. BOX 4004  
BURLINGTON, NORTH CAROLINA 27215  
PHONE (336) 227-7710 • FAX (336) 227-1175  
[www.diversifiedtestinglabs.com](http://www.diversifiedtestinglabs.com)

March 6, 2024

Mr. Claude Simon  
VERATEX, INC.  
P.O. Box 682  
New York, NY 10108

Reference: Laboratory Test Report  
Lab Identification No. 58818  
Invoice No. 90127

Dear Mr. Simon:

One (1) fabric sample, identified as **Style: V81440; Lot: 18343/304482**, was received and tested in accordance with ASTM D 6413-15, “Standard Test Method for Flame Resistance of Textiles (Vertical Test)”. The results are as follows:

**Test Results**

Specimen Number	After Flame (seconds)		After Glow (seconds)		Char Length (inches)	
	<u>Length</u>	<u>Width</u>	<u>Length</u>	<u>Width</u>	<u>Length</u>	<u>Width</u>
1	0.0	0.0	0.0	0.0	3.6	4.3
2	0.0	0.0	0.0	0.0	4.1	5.2
3	0.0	0.0	0.0	0.0	5.4	4.6
4	0.0	0.0	0.0	0.0	4.5	4.5
5	<u>0.0</u>	<u>9.0</u>	<u>0.0</u>	<u>0.0</u>	<u>5.2</u>	<u>5.9</u>
<b>Avg</b>	<b>0.0</b>	<b>1.8</b>	<b>0.0</b>	<b>0.0</b>	<b>4.6</b>	<b>4.9</b>

Note: There were no occurrences of melting or drippings.

Sincerely,

Brian S. Dement

BSD/mr

