



Detailed Photos  
For  
534 West 42<sup>nd</sup> Street, Manhattan NY  
Dated May 22, 2018

534 West 42<sup>nd</sup> Street, NYC  
Bin # 1088887, Control # 816577  
Block # 1070, Lot # 7502  
May 22<sup>nd</sup>, 2018  
Page 2



Photo 1. Front Entrance of Building

**534 West 42<sup>nd</sup> Street, NYC**  
**Bin # 1088887, Control # 816577**  
**Block # 1070, Lot # 7502**  
**May 22<sup>nd</sup>, 2018**  
**Page 3**



Photo 2. Close-up inspection of North Façade via electric scaffold



Photo 3. Cracks in setback parapet 8<sup>th</sup> floor, north elevation.




Photo 4. Split caulking at building joint line.




Photo 5. Vertical crack at interior of parapet.

534 West 42<sup>nd</sup> Street, NYC  
Bin # 1088887, Control # 816577  
Block # 1070, Lot # 7502  
May 22<sup>nd</sup>, 2018  
Page 6



Photo 6. Roof Parapet measuring 50 inches in height.

534 West 42<sup>nd</sup> Street, NYC  
Bin # 1088887, Control # 816577  
Block # 1070, Lot # 7502  
May 22<sup>nd</sup>, 2018  
Page 7



Photo 7. Balcony railing measuring 42 inches in height.