




75 Spring Street 6th Flr
New York, NY 10002
212.334.7402
Fax 212.334.6112



3	Construction Set Revisions as Noted	01.26.07
2	Construction Set Revisions as Noted	11.30.06
1	Construction Plans and Elevations	10.30.06

No.	Revision/Issue	Date
-----	----------------	------

DEUCE CONDOMINIUM
534 WEST 42ND STREET
New York NY 10036

ELEVATIONS - INFILL WALL

Scale	AS SHOWN	Sheet No. A431
Date	11.30.06	
Drawn By	R.R.	