



## NOTICE TO CALL FOR INSPECTION

TO OWNER OR OCCUPANT OF 534 WEST 42<sup>ND</sup> ST MANHATTAN  
(House Number, Street Name, Borough)

An attempt was made to inspect the above-referenced premises on 06/08/2021 at  
11:00  a.m. /  p.m., in reference to complaint #(s): UNSAFE FAÇADE REPORT  
in order to ensure compliance with the New York City Building Code, Zoning  
Resolution, Multiple Dwelling Law, Housing Maintenance Code, Plumbing Code,  
Electrical Code and other applicable laws.

You are hereby requested to contact the New York City Department of Buildings to  
arrange a date when these premises may be inspected.

*REQUIRE ACCESS TO ROOF AND REAR OF BUILDING*

**FAILURE TO COMPLY WITH THIS NOTICE  
MAY RESULT IN THE DEPARTMENT OBTAINING AN ACCESS WARRANT  
AUTHORIZING THE INSPECTION OF THE PREMISES.**

*Facade inspections @ buildings.nyc.gov*

Please contact the Facades Unit at 212 393 2551, located at  
(Unit Name) (Unit Contact Number)

280 Broadway Manhattan, to make an appointment for an Inspection.  
(Office Address of Responding Unit)

Thank you for your prompt attention to this matter.

**New York City Department of Buildings**

---

**Contact Us**

<https://www1.nyc.gov/site/buildings/about/contact-us.page>

Inspector Name:

*T Fallon*  
(PRINT FIRST INITIAL & LAST NAME)

Badge No.:

*2864*

Inspector Name:

(PRINT FIRST INITIAL & LAST NAME)

Badge No.: