

The City of New York
Department of Buildings**Exterior Wall Condition Certificate****STATUS : SAFE****LOCATION:****534**

Building Number

WEST 42 STREET

Street Address

MANHATTAN

Borough

1088887

BIN (Building Identification Number)

QEWI NAME:**STEVEN GAMBINO**

QEWI (Qualified Exterior Wall Inspector)

RA - 022172

License Number

RODRIGUEZ + GAMBINO ARCHITECTURAL

QEWI Business Name

LAST QEWI INSPECTION DATE:**2026-03-12****SWAMP/UNSAFE DATE:****The repairs to the exterior walls of the building at the above listed
address will be complete by: N/A***NOTE: For a building that files as 'SAFE' this information is not a requirement.**This certificate must be displayed in the lobby or public space of the
building identified in LOCATION.*