

PREMISES

534 W 42nd Street, New York, NY

SPRINKLER EQUIPMENT IN THIS BUILDING IS INSPECTED MONTHLY

CERTIFICATE OF FITNESS HOLDER Patrick Sullivan CERTIFICATE # 86518834 EXP. DATE 9/10/2020YEAR 2020

MONTH	VALVES LOCKED	EXTRA SPK HEADS	ARE SIGNS IN PLACE	CONDITION OF SPRINKLER PIPING	CONDITION OF SPRINKLER HEADS	SIAMESE CONNECTION	ALARM DEVICE	WATER PRESSURE	INITIALS & NOTES
JAN	✓	✓	✓	OK	OK	OK	OK	90	✓
FEB	✓	✓	✓	OK	OK	OK	OK	92	✓
MAR	✓	✓	✓	OK	OK	OK	OK	90	✓
APR	✓	✓	✓	OK	OK	OK	OK	130	✓
MAY	✓	✓	✓	OK	OK	OK	OK	127	✓
JUN	✓	✓	✓	OK	OK	OK	OK	153	✓
JUL	✓	✓	✓	OK	OK	OK	OK	135	✓
AUG	✓	✓	✓	OK	OK	OK	OK	139	✓
SEPT	✓	✓	✓	OK	OK	OK	OK	135	✓
OCT	✓	✓	✓	OK	OK	OK	OK	140	✓
NOV	✓	✓	✓	OK	OK	OK	OK	140	✓
DEC	✓	✓	✓	OK	OK	OK	OK	151	✓

- Assure siamese connection(s) are not blocked and caps are in place and painted appropriately.
- If valves are locked note "yes" if they are not locked, relock and note "locked."
- Inspect alarm valve to assure no leakage from retard chamber or alarm drain.
- Assure there is proper number and type of extra sprinkler heads and wrench.